



10/ 644417

COFE

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: Jack Hwang et al.

Patent No.: 6,911,706

Issued: June 28, 2005

For: Forming Strained Source Drain  
Junction Field Effect Transistors

§  
§  
§  
§  
§  
§  
§

Group Art Unit: 2822

Examiner: M. Prenty

Atty. Dkt. No.: ITL.0764D1US

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Attn: Decision and Certificate of Correction  
Branch of the Patent Issue Division


**Certificate**  
JUL 28 2005  
of Correction

**REQUEST FOR CERTIFICATE OF CORRECTION  
OF PATENT FOR PTO MISTAKE  
(37 C.F.R. § 1.322(a))**

1. Attached, in duplicate, is Form PTO-1050, with at least one copy being suitable for printing.
2. The exact page and line number where the error is shown correctly in the application file is in the "Reply to Paper No. 20050125", filed May 1, 2005, page 2, claim 22 (renumbered in the printed patent to claim 3), line 1.
3. Please send the Certificate to:

Timothy N. Trop  
TROP, PRUNER & HU, P.C.  
8554 Katy Freeway, Suite 100  
Houston, Texas 77024-1805

JUL 29 2005


Date of Deposit: 7-22-05
I hereby certify under 37 CFR 1.8(a) that this correspondence is being deposited with the United States Postal Service as first class mail with sufficient postage on the date indicated above and is addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Sherry Tipton

4. All errors sought to be corrected were made in printing by the Patent and Trademark Office and no fee is believed to be due.

Respectfully submitted,

Date: \_\_\_\_\_

7/22/05



\_\_\_\_\_  
Timothy N. Trop, Registration No. 28,994  
TROP, PRUNER & HU, P.C.  
8554 Katy Freeway, Ste. 100  
Houston, TX 77024  
713/468-8880 [Phone]  
713/468-8883 [Fax]

# UNITED STATES PATENT AND TRADEMARK OFFICE

## CERTIFICATE OF CORRECTION

PATENT NO. : US 6,911,706 B2

DATED : June 28, 2005

INVENTOR(S) : Jack Hwang, Craig Andyke, Mitchell Taylor

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4:

Line 11, after "3. The" insert --circuit--.

MAILING ADDRESS OF SENDER (Please do not use customer number

Timothy N. Trop  
Trop, Pruner & Hu, P.C.  
8554 Katy Freeway, Suite 100  
Houston, TX 77024

PATENT NO. US 6,911,706 B2

No. of additional copies



JUN 29 2005